

FIG. 1

1/4

10°




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6





FIG. 7

A perspective view of a repair slot assembly 10. The assembly includes a substrate 20 with a repair slot 24. A repair material 100 is applied to the bottom surface of the slot. A repair layer 30 is formed on top of the repair material. A repair cap 110 is positioned over the repair layer. A repair cap 112 is also shown. A repair cap 110 is labeled "NOT USED". A repair cap 110 is labeled "LS".

[illegible]